BARE FIBER ADAPTER

Description

Bare fiber adapter is mainly used in insertion loss test of optical pigtails and all kinds of devices. As long as a simple assembly of the bare fiber and fiber adapters,it can be finished at the other end or whole fiber insertion loss test.Reusable is the basic function of bare fiber adapters,KOC provide bare fiber adapters four main types of SC, FC, LC and ST, all the number of repeated use of more than one thousand times.Simple and easy to assemble, small size, durable, long life, is one of the indispensable to optical fiber testing device.

Applications

· Fiber optic link test
· The production workshop components test
· Temporary test equipment, and links
· Test equipment
· FTTX

Features

· Various receptacle type
· Automatic clamping device
· Easy to operate
· Repeated use

Specification

Item	Specification
Insertion Loss	<1.0dB
Repeatability	<0.20 dB typical change
Life time	≥1000 times
Ferrule ID	Φ125.5um/φ126.0 um
Working Temperature	-20 to + 75°C
Operating Temperature	-40 to + 85°C

Order Information

PN	Description
120-0103-101	FC SM Bare Fiber adapter , METAL

FC SM Bare Fiber adapter

Note: Such as demand and conventional standard is different, can produce products according to customer's requirements .

FIBER OPTIC COMPONENTS GLOBAL SUPPLIER

KOC Group

PN	Description
122-0103-102	FC SM Bare Fiber adapter , METAL ， Square

FC SM Bare Fiber adapter ，Square

PN	Description
122-0903-101	SC SM Bare Fiber adapter , METAL

SC SM Bare Fiber adapter

PN	Description
122-0903-102	SC SM Bare Fiber adapter , METAL ， Square

SC SM Bare Fiber adapter ， Square

PN	Description
122-1803-101	LC SM Bare Fiber adapter , METAL ， Square

LC SM Bare Fiber adapter ，Square

PN	Description
122-3603-101	ST SM Bare Fiber adapter , METAL ， Square

ST SM Bare Fiber adapter ，Square

Note: Such as demand and conventional standard is different, can produce products according to customer's requirements .